Ruamahanga River: Nutrient and Algal Periphyton Monitoring in Relation to the Masterton Wastewater Discharge

NIWA Client Report: HAM2003-154 December 2003

NIWA Project: BCH03207

Ruamahanga River: Nutrient and Algal Periphyton Monitoring in Relation to the Masterton Wastewater Discharge: Appendix 3

C. W. Hickey

Prepared for

Beca Carter Hollings & Ferner Ltd

NIWA Client Report: HAM2003-154 December 2003

NIWA Project: BCH03207

National Institute of Water & Atmospheric Research Ltd Gate 10, Silverdale Road, Hamilton P O Box 11115, Hamilton, New Zealand Phone +64-7-856 7026, Fax +64-7-856 0151 www.niwa.co.nz

[©] All rights reserved. This publication may not be reproduced or copied in any form without the permission of the client. Such permission is to be given only in accordance with the terms of the client's contract with NIWA. This copyright extends to all forms of copying and any storage of material in any kind of information retrieval system.

Contents

Appendix 3: Photographic data Survey: 4 February 2003 Survey: 17 February 2003 Survey: 4 March 2003 Survey: 17 March 2003 Survey: 2 April 2003 Survey: 15 April 2003

Error! Bookmark not defined. 2

1

Reviewed by:

Approved for release by:

Dr M. Scarsbrook

Dr S. Clearwater

Appendix 3: Photographic data

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix



Rua 1



Rua 1-1









Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 3









Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 4



Rua 1-6



Rua 1-7

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 5



Rua 1-8



Rua 1 tiles

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 6

Survey: 15 April 2003



Rua 1 tiles 2



Rua 1 tiles 3

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 7



Rua 1B-1




Rua 1B-2



Rua 1B-3




Rua 1B-4







Rua 2-2



Rua 2-3



Rua 2-5

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix



Rua 2-6




Rua 2-7

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 12



Rua 2-8



Rua 2-9

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 13



Rua 2B-1



Rua 2B-2




Rua 2B-3



Rua 2B-5



Rua 2B-6



Rua 2B-7



Rua 2B-8



Rua 2 tiles 2

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 17



Rua 2 tiles



Rua 3

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 18



Rua 3-1



Rua 3-2

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 19







Rua 3-4

Ruamahanga River: Nutrient and Algal Periphyton monitoring in relation to the Masterton Wastewater Discharge: Appendix 20



Rua 3-5